



TEST REPORT

Page 1 of 3

REPORT NUMBER: TURT180230122 **APPLICANT NAME:** Işın Mumcu Artisan

ADDRESS: Emirgan Mh. Posta Yolu Cd. No:123 Sarıyer İstanbul / TURKEY

TEL:0533 518 89 18

Attention: Işın Mumcu (mumcu67@gmail.com)

One sample of PAMUKKALE 00010718 CP-0001 CHALK PAINT Liquid item **SAMPLE DESCRIPTION:**

DATE IN: 18 December ,2018 (08:05:00)

DATE OUT: 20 December ,2018

TRADE NAME: PAMUKKALE 00010718 CP-0001 CHALK PAINT

	SAMPLE
TEST	1
Migration of Certain Elements	Р

P = MEETS BUYER' S REQUIREMENT / F = DOES NOT MEET BUYER' S REQUIREMENT / NR = NO REQUIREMENT / SC=STILL CONTINUES / X=NOT PERFORMED / NA = NOT APPLICABLE / LS = LACK OF SAMPLE / NC = NO COMMENT / I = INCONCLUSIVE / # = SEE RESULT / NF = NEEDS FURTHER TESTING / A = ABSENT / M = MARGINAL ACCEPT / SD = SEE **DETAILS ENCLOSED / FS: FURTHER STEPS**

This report (including any enclosures and attachments) are prepared for the exclusive use of the Customer(s) named in the report and solely for the purpose for which it is This report (including any enclosures and attachments) are prepared for the exclusive use of the Customer(s) named in the report and solely for the purpose for which it is provided and on the basis of instructions and information and/or materials supplied by Intertek's Customer. The test results relate only to the specific items tested and are not intended to be a recommendation for any particular course of action. Customer is responsible for acting as it sees fit on the basis of such results. Unless Intertek provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Intertek do not accept any liability if this report is used for an alternative purpose from which it is intended, nor do Intertek owe any duty of care to any third party in respect of this report. Except where explicitly agreed in writing, all work and services performed is governed by Intertek Standard Terms and Conditions of Service which is available on request or can be obtained at http://www.intertek.com/terms. The reported uncertainty is based on a standard uncertainty multiplied by a coverage factor k=2, providing a level of confidence of approximately 95%. The uncertainty evaluation has been carried out in accordance with ISO/IEC 17025 and TÜRKAK accreditation requirements. Unless otherwise is specified, all Pass or Fail results are given without uncertainty considered. When uncertainty is taken into account, the result may be borderline. Borderline results need to be re-tested to determine their disposition up to customer's decision. Opinions and interpretations expressed herein are outside the scope of TÜRKAKA accreditation. Tests re-tested to determine their disposition up to customer's decision. Opinions and interpretations expressed herein are outside the scope of TÜRKAK accreditation. Tests marked (*) in this test report are not included in the TÜRKAK accreditation schedule for this laboratory.

Mert KURTULUS Burcu KESKİNSOY KUNDAKÇI

Customer Care Executive

Zeynep AKIN

Chemical Laboratory Manager

Intertek Test Hizmetleri A.S.

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL Phone: +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail: intertekcg.turkiye@intertek.com http://www.intertek-turkey.com







R E S U L T S Page 2 of 3
REPORT :TURT180230122 20 December ,2018

Test Method Results Requirements

Migration of Certain Elements

BS EN 71-3:2013+A3:2018

Acid extraction method was used and migration elements content were determined by Inductively Coupled Plasma-ICP MS

	Result	Detection Limit	Requirement
Antimony (Sb)	Not Detected	0.125 ppm	11.3 ppm
Arsenic (As)	Not Detected	0.125 ppm	0.9 ppm
Barium (Ba)	1.0 ppm	0.125 ppm	375 ppm
Cadmium (Cd)	Not Detected	0.125 ppm	0.3 ppm
Chromium (III)**	Not Detected	0.125 ppm	9.4 ppm
Chromium (VI)**	Not Detected	0.005 ppm	0.005 ppm
Lead (Pb)	Not Detected	0.125 ppm	3.4 ppm
Mercury (Hg)	Not Detected	0.0125 ppm	1.9 ppm
Selenium (Se)	Not Detected	0.125 ppm	9.4 ppm
Aluminium (AI)	0.9 ppm	0.125 ppm	1406 ppm
Boron	2.8 ppm	0.125 ppm	300 ppm
Cobalt (Co)	Not Detected	0.125 ppm	2.6 ppm
Copper (Cu)	Not Detected	0.125 ppm	156 ppm
Manganese (Mn)	0.6 ppm	0.125 ppm	300 ppm
Nickel (Ni)	Not Detected	0.125 ppm	18.8 ppm
Strontium (Sr)	11.8 ppm	0.125 ppm	1125 ppm
Tin (Sn)	Not Detected	1.25 ppm	3750 ppm
Organic tin**	Not Detected	0.125 ppm	0.2 ppm
Zinc (Zn)	Not Detected	0.125 ppm	938 ppm

^{* * =} Unless the test results were marked with "#" or "Δ", Chromium (III) & Chromium (VI) and Organic tin contents were not directly determined and were derived from migration results of total chromium and tin respectively.

 Δ = Confirmation test was performed on the tested component. The reported value was the sum of the migration values of Methyl tin, Butyl tin, Dibutyl tin, Tributyl tin, Tetrabutyl tin, n- Octyl tin, Di-n-octyl tin, Di-n-propyl tin, Diphenyl tin and Triphenyl tin after converted to Tributyl tin by calculation. Other Organic tin compounds may be also be present in sample as stated in EN71-3:2013+A1:2014.

ppm (Part per million) = mg/kg < = Less Than ND = Not Detected

Estimated Total Uncertainity=(±17%)

^{# =} Confirmation of Chromium (VI) test was performed on the tested component. And the reported value of migration of Chromium (III) = migration value of total Chromium - migration value of Chromium(VI).





RESULTS
REPORT:TURT180230122

Page 3 of 3 20 December ,2018



END OF TEST REPORT